

**Tank Storage Status**  
Version Date: 4/11/19

**Table 1: Response Tanks Storing Collected Response Liquids**

Tank #	Material Stored	Tank Max Capacity (bbbls)	Current Level - Total (bbbls)	Water Level (bbbls)	Organic Total (bbbls)	Comment/Activity
80-18	Firefighting Water/Organics	71,508	67,841	23,906	43,935	No Activity
80-33	Firefighting Water/Organics	72,528	43,129	12,687	30,442	Active via Vacuum Trucks
100-28	Firefighting Water/Organics	100,297	36,626	20,633	15,993	Active via Vacuum Trucks
100-31	Firefighting Water/Organics	100,255	99,923	90,710	9,213	No Activity
100-15	Firefighting Water/Organics	100,256	76,934	60,298	16,636	Active via Tank farm draining
100-1	Firefighting Water/Organics	100,074				No Activity; Ready to receive material
		544,918	324,453	208,234	116,219	

**Table 2: ITC Wastewater System Tanks**

Tank #	Material Stored	Tank Max Capacity (bbbls)	Current Level - Total (bbbls)	Water Level (bbbls)	Organic Total (bbbls)	Comment/Activity
50-2	Prior Wastewater/Firefighting Water/Organics	52,084	50,889	50,712	177	
80-34	Prior Wastewater/Firefighting Water/Organics	80,287	56,801	53,862	2,939	
60-1	Prior Wastewater/Firefighting Water/Organics	54,384	50,578	44,483	6,095	
		186,755	158,268	149,057	9,211	

**Table 3: Temporary Storage Vessels Loaded**

Barge	Prior Wastewater/Firefighting Water/Organics	57,000	49,157	49,157		

**Table 2: Impacted Tank Farm Information**

Tank #	Material Stored Prior to Event	Safe Operating Capacity (bbbls)	Current Level - Total (bbbls)	Quantity Prior To Event (bbbls)	Comment/Activity	Physical Status Of The Tank
80-1	Base Oil	72,978	3,100	49,760	Product removal in progress; tank leaking into containment	Tank erect, charred, damage to roof
80-2	Gas Blendstock	74,189	Residual	42,260	Clean and Complete	Collapsed
80-3	Gas Blendstock	69,679	Residual	33,410	Cleaning In Progress	Tank erect, charred, but heavily damaged
80-4	Base Oil	74,497	1,500	35,699	Product removal in progress; tank leaking into containment	Tank erect, charred, damage to roof
80-5	Xylene	72,859	100	38,426	Cleaning In Progress	Collapsed
80-6	Gas Blendstock	74,789	100	49,414	Cleaning In Progress	Collapsed
80-7	Pygas	75,373	3,000	43,595	Liquid - Firewater / Organic Mix - Product Removal Ongoing	Half of the tank standing, roof collapsed
80-8	Naphtha	73,960	1,500	70,761	Organic Removal Ongoing	Collapsed
80-9	EMPTY	76,521	NA	Empty	Open and Complete	Collapsed
80-10	Pygas	74,767	1,100	14,382	Degassing; Product removal in progress	Erect, fixed roof in tact
80-11	Base Oil	76,208	22,000	52,902	Organics transferred initially. Flanges leaking to Tank Containment	Erect, charred, and damage to roof
80-12	EMPTY	76,502	NA	Empty	Open and Complete	Partially Collapsed
80-13	Toluene	70,523	1,400	14,725	Degassing	Erect, fixed roof in tact
80-14	Pygas	72,965	100	15,840	Degassing; Sludge in tank	Collapsed
80-15	Pygas	74,692	100	9,421	Degassing; Sludge removal in progress	Collapsed
		1,110,502	34,000	470,595		

	Full of Product / No action	EMPTY	No organics in the tank
	Bulk Organic Removed	Clean	Tank has no organics and has been rinsed and cleaned
	Heel / Residual Remaining - In Process	Ready to Clean	Product removed, man ways open, and ready for tank cleaning to begin
	Clean Or Liquid and Gas Free		